| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|---|---|---|---|---|---|---|
| L11 | 4578 | pull near3 (cable thread wire fiber line yarn).clm. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:50 |
| L12 | 226 | 11 and hydraulic$5.clm. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:48 |
| L13 | 15 | 12 and ((tension force load stress) near3 (test$5 detect$5 sens$5 estimat$5 evalut$5 determin$5 measur$5 transducer cell meter gauge monitor$5 )).clm. | USPAT; EPO; JPO | OR | ON | 2004/12/10 16:51 |
| L14 | 5 | 11 and hydraulic$5 near3 jack. clm. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:47 |
| L15 | 1901 | 11near6 hydraulic$5 near3 jack. clm. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:48 |
| L16 | 0 | 11 near6 hydraulic$5 near3 jack. clm. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:48 |
| L17 | 0 | 11 near9 hydraulic$5 near3 jack. clm. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:48 |
| L18 | 0 | 11 near9 hydraulic$5 near3 jack | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:49 |
| L19 | 2314 | 11and hydraulic$5 near3 jack.clm. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:49 |

| L20 | 5 | 11 and hydraulic$5 near3 jack. clm. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:53 |
|---|---|---|---|---|---|---|
| L21 | 53 | pull$5 near3 (cable thread wire fiber line yarn) near5 (Hydraulic$5 near3 jack) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:50 |
| L22 | 3 | pull$5 near3 (cable thread wire fiber line yarn) near5 (Hydraulic$5 near3 jack).clm. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:50 |
| L23 | 0 | 22 and ((tension force load stress) near3 (test$5 detect$5 sens$5 estimat$5 evalut$5 determin$5 measur$5 transducer cell meter gauge monitor$5 )) | USPAT; EPO; JPO | OR | ON | 2004/12/10 16:52 |
| L24 | 1 | 22 and ((tension force load stress)).clm. | USPAT; EPO; JPO | OR | ON | 2004/12/10 16:52 |
| L25 | 23 | pull$5 near5 hydraulic$5 near3 jack.clm. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:53 |
| L26 | 9 | 25 and cable | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/12/10 16:53 |